Mount Vernon Fairfax County, Virginia

HABS VA 30-\_\_\_ 2-

ADDENDUM FOLLOWS...

**PHOTOGRAPHS** 

Historic American Buildings Survey Eugene Bradbury, District Officer Upperville, Virginia Addendum to
Mount Vernon
.2 mile south of Mount Vernon
Memorial Highway, at intersection with State Route 235
Mount Vernon
Fairfax County
Virginia

HABS VA, 30-\_\_\_,

ADDENDUM FOLLOWS...

**PHOTOGRAPHS** 

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

Form 10-920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS VA, 30-\_\_\_\_

## ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VI	VICINITY	
Virginia	Fairfax		Mount Ver	ount Vernon	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)				HABS NO.	
Mount Vernon				VA-505	
SECONDARY OR COMMON NAMES OF STRUCTURE					
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)					
.2 mile south of Mount Vernon Memorial Highway, at intersection of State Route 235					
OATE OF CONSTRUCTION (INCLUDE SOURCE)		ARCHITECT(S) (INCLUDE SOURCE)			
begun ca. 1730					
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)  Originally home of Augustine Washington, George Washington's father, it became the first president's home from 1754 until his death in 1799. Became the object of America's first successful nationwide preservation effort when restored by the Mount Vernon Ladies Association of the Union in 1858.  STYLE (IF APPROPRIATE)  Georgian					
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)					
Frame; beveled-edged wood siding resembling rusticated stonework					
HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) 96' (9-bay front) x 32' (not including portico; 2½-story; hipped roof with octagonal cupola 2-story portico with 8 square pillars extending width of east front CONTINUED  EXTERIOR FEATURES OF NOTE  Modillion cornice; modillion cross gable with elliptical lunette on the west front; entrance doorway with architrave frame supporting a frieze and pediment; Palladian window on north facade					
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)					
Center-hall plan; notable interior trim and ornamental plaster decoration					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES When first begun, ca. 1730, was $1\frac{1}{2}$ -story house. Enlarged to $2\frac{1}{2}$ -story 1758-59; south end extended 1775; north end extended 1776; east portico completed 1777; west cross gable completed 1778; octagonal cupola added 1787; restored 1858.					
PRESENT CONDITION AND USE					
Condition excellent; used as historic house museum.					
OTHER INFORMATION AS APPROPRIATE					
Catalog. 1976.  A National Historic Landmark					
COMPILER, AFFILIATION				DATE	
Druscilla J. Null, HABS				8/1/83	

MOUNT VERNON
HABS No. VA-505 (Page 2)
Architectural Data Form

## SHAPE AND DIMENSIONS OF STRUCTURE (Continued)

 $1\frac{1}{2}$ -story dependencies connected to main house by quarter circle covered arcades; notable brick and frame outbuildings forming complete plantation complex; notable landscaping and gardens.

Addendum to
Mount Vernon
.2 mile south of Mount Vernon
Memorial Highway, at intersection
with State Route 235
Mount Vernon
Fairfax County
Virginia

HARS VA,

PHOTOGRAPH

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240